












instruction

1027 05 16 11
102 / 2








instruction





1027 05 16 53
308/2


M10

M12




H+





1




2

+ = 180°




++ = 360°

MAX. +++ = 720°



ADJUSTABLE


3





+ = 180°

++ = 360°

MAX. +++ = 720°



ADJUSTABLE



instruction

1027 05 13 42

1027 05 16 53
308/2